

# BELZONA HELPS SWEET MANUFACTURER AGAIN AFTER 8 YEARS

ID: 737

Industry: *General Industry*  
 Application: *TCC-Tanks and Chemical Containment Areas*  
 Substrate: *Steel & Belzona® 1321*  
 Products: *\* Belzona® 1321 (Ceramic S-Metal),*

Customer Location: *Sweet Manufacturer, Belgium*  
 Application Date: *September 2005*

## Problem

*The Belzona coating, applied 8 years previously, was still in good condition and had only suffered some discolouration. The client, however, wanted to apply a fresh coat of Belzona.*



## Photograph Descriptions

- \* 8-year-old Belzona® 1321 coating ,
- \* Another view of 8-year-old Belzona® 1321 coating ,
- \* New Belzona® 1321 coating ,
- \* Coated hatch ,

## Application Situation

Mixing tank

## Application Method

The Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

## Belzona Facts

The client was so pleased that the original Belzona coating lasted 8 years that they once again contacted Belzona to re-coat the machine.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
 FS 695214  
 ISO 14001:2015  
 EMS 695213

Belzona products are  
 manufactured under an ISO  
 9000 Registered Quality  
 Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
 Repair • Protect • Improve