

BELZONA MANWAY OPENING

ID: 74

Industry: Chemical & Petrochemical
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Stainless Steel
Products: * Belzona® 1111 (Super Metal) ,

Customer Location: Petroleum Refinery in Texas
Application Date: 1991

Problem

Opening on chemical tank was corroded to the point where a good seal was not possible.



Photograph Descriptions

- * Surface preparation performed with the repair area taped off. ,
- * Manway rebuilt. ,

Application Situation

Manway opening on chemical storage tank.

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet TCC-10.

Belzona Facts

For only \$128 in Belzona® 1111 (Super Metal), downtime and expensive welding was averted. The repair has held for many years, and is still in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve