

BELZONA REPAIRS A VERY LARGE PUMP HOUSING

ID: 745

Industry: *Power*
Application: *CEP-Centrifugal Pumps*
Substrate: *Steel and Concrete*
Products: *Belzona® 1111 (Super Metal)*

Customer Location: *Power Plant, France*
Application Date: *July 2002*

Problem

Water infiltration between joint of metal and concrete



Photograph Descriptions

* Application Situation , * Cleaning , * Application of Belzona® 1111 (Super Metal) ,

Application Situation

Large cooling water pump housing

Application Method

The application was carried out in accordance with a modified Belzona Know-How System Leaflet CEP-5.

Belzona Facts

Other solutions were considered implausible by the client who was delighted when Belzona® came up with a solution

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve