

# BELZONA REPAIRS A VERY LARGE PUMP HOUSING

ID: 745

Industry: *Power*  
Application: *CEP-Centrifugal Pumps*  
Substrate: *Steel and Concrete*  
Products: *Belzona® 1111 (Super Metal)*

Customer Location: *Power Plant, France*  
Application Date: *July 2002*

## Problem

*Water infiltration between joint of metal and concrete*



## Photograph Descriptions

\* Application Situation , \* Cleaning , \* Application of Belzona® 1111 (Super Metal) ,

## Application Situation

Large cooling water pump housing

## Application Method

The application was carried out in accordance with a modified Belzona Know-How System Leaflet CEP-5.

## Belzona Facts

Other solutions were considered implausible by the client who was delighted when Belzona® came up with a solution

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve