

PUMP SUMP PROTECTION WITH BELZONA ON OIL TANKER

ID: 748

Industry: Marine
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Steel
Products: Belzona® 1391 (Ceramic HT Metal)

Customer Location: Oil Tanker owner, Palermo, Italy
Application Date: February 2006

Problem

Erosion/Corrosion due to the constant liquid flow over the sump during cargo transfer.



Photograph Descriptions

* The tanker in dock. , * Sump after blasting. , * Sump coated with Belzona® 1391. , * Completing the application. ,

Application Situation

Sumps (suction wells) located underneath "Elephants feet" in cargo tanks.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

Belzona Facts

This is a standard application carried out by a variety of owners and ship builders. The use of Belzona in this instance minimised dry-docking time. The Belzona® 1391 provides excellent erosion resistance when handling heated cargo.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025