

# PUMP SUMP PROTECTION WITH BELZONA ON OIL TANKER

ID: 748

Industry: *Marine*  
Application: *TCC-Tanks and Chemical Containment Areas*  
Substrate: *Steel*  
Products: *Belzona® 1391 (Ceramic HT Metal)*

Customer Location: *Oil Tanker owner, Palermo, Italy*  
Application Date: *February 2006*

## Problem

*Erosion/Corrosion due to the constant liquid flow over the sump during cargo transfer.*



## Photograph Descriptions

\* The tanker in dock. , \* Sump after blasting. , \* Sump coated with Belzona® 1391. , \* Completing the application. ,

## Application Situation

Sumps (suction wells) located underneath "Elephants feet" in cargo tanks.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

## Belzona Facts

This is a standard application carried out by a variety of owners and ship builders. The use of Belzona in this instance minimised dry-docking time. The Belzona® 1391 provides excellent erosion resistance when handling heated cargo.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve