

Belzona Protects Screw Conveyor against Abrasion

ID: 7486

Industry: Power

Customer Location: Biomass power plant, France

Application: SHM-Solids Handling Machinery

Application Date: June 2015

Substrate: Steel

Products: * Belzona 1311(Ceramic R-Metal) Belzona 1341 (Supermetalgilde) Belzona 9811 ,

Problem

Abrasion of welds. Welding of the screw every 12 months. Service life: 5 years



Photograph Descriptions

- * 1. Grit-blasted screw conveyor ,
- * 2. Application of ceramic tiles on Belzona 1311 ,
- * 3. Finished application ,

Application Situation

11 meter long stainless steel screw conveyor, tube Ø 700 for the transport of wood bark.

Application Method

The surface was grit-blasted and a layer of Belzona 1311 was applied. Ceramic tiles were placed and coated with Belzona 1311. The surface was then grit-blasted and Belzona 1341 was applied in 2 layers.

Belzona Facts

Visit after 12 months: no visible abrasions or tile detachment

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve