

BELZONA REPAIRS AND PROTECTS CYANIDE CONTAINMENT AREA

ID: 7501

Industry: *Mining & Quarrying*

Customer Location: *Gold mine, Mauritania*

Application: *FPA-Floor Problem Areas*

Application Date: *August 2016*

Substrate: *Concrete*

Products: ** Belzona 4131 (Magma Screed) ,*

Problem

Concrete pump plinths and the containment areas needed protection against chemical attack to avoid spalling and potential contamination of the ground due to loss of containment.



Photograph Descriptions

* 1. Chemical storage tanks area. 2. Application of Belzona 4131 to walls and concrete plinths in progress 3. Containment area rebuilt and protected with Belzona 4131 ,

Application Situation

Containment area for Cyanide tanks and pumps.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 and FPA-3.

Belzona Facts

All repair work was carried out quickly without interrupting production plans which are especially critical in the mining sector. Contractor supervising the works with Belzona 4131 reported that after one year the applications were all in perfect condition. End customer is currently undertaking new repair jobs to resurface and protect concrete areas exposed to potential chemical attack.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com


BELZONA
 Repair • Protect • Improve