

# Parks and Recreation Restroom Floor Coated with Belzona

ID: 7505

Industry: *Buildings & Structures*  
Application: *FPA-Floor Problem Areas*  
Substrate: *Concrete*  
Products: *\* Belzona 5811 (Immersion Grade) ,*

Customer Location: *Montana, USA*  
Application Date: *May 2017*

## Problem

*Customer has numerous restrooms in public areas that are porous and cannot be disinfected efficiently.*



## Photograph Descriptions

- \* Performing floor grinding preparation ,
- \* Surface edge and floor grinding complete ,
- \* Belzona 5811 application complete ,

## Application Situation

Rest area needed to be sealed to allow cleaning and disinfecting of public access area. Porous concrete can harbor biological growth.

## Application Method

The application was carried out in accordance with a modified version of Belzona System Leaflet FPA-3. The floor was ground with diamond grinders. Within the overcoat windows two full coats of Belzona 5811 were applied.

## Belzona Facts

The hard sealed surface allows cleaning crews to clean the restroom much easier, saving man hours and chemical use. Applying the Belzona coating has made the public access safer, cleaner and more pleasant.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve