

Belzona Seal-A-Tank Success in Service for Over 13 Years

ID: 7530

Industry: Oil & Gas
 Application: TCC-Tanks and Chemical Containment Areas
 Substrate: Steel
 Products: * Belzona 3111 (Flexible Membrane),

Customer Location: Refinery, West France
 Application Date: 2004

Problem

The refinery had an existing tank base sealing system in place which was failing due to its rigidity. The failed system had resulted in water ingress, causing corrosion at the base of the tank and required protection for the long term.



Photograph Descriptions

- * 1. Failing system that needed replacing. ,
- * 2. Surface conditioned. ,
- * 3. Testing the annular rim through Belzona 3111. ,
- * 4. Seal-a-Tank system still in an excellent condition. ,

Application Situation

Tanks at a refinery in West France were suffering from water ingress.

Application Method

Application completed in accordance with Belzona Know How System Leaflet TCC-4. Surface correctly prepared and conditioned before the application of Belzona 3111 to provide waterproof protection at the base of the tank.

Belzona Facts

This application was inspected three years after and found to be in good condition with no signs of corrosion. Subsequently, it was reinspected in 2017 and still found to be in excellent condition. The customer was very pleased with the application and its longevity in service. In addition, the customer was pleased because, unlike competitor systems, it is possible to inspect the thickness of the annular rim through Belzona 3111.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com


BELZONA
 Repair • Protect • Improve