

PROTECTING HVAC DUCTWORK WITH BELZONA

ID: 7534

Industry: Heating, Ventilation & Air Conditioning

Customer Location: France

Application: VPF-Valves, Pipes and Fittings


Application Date: 2003

Substrate: Various insulation materials

Products: * Belzona 3211 (Lagseal) ,

Problem

Solution required to seal and protect weathered ductwork insulation.



Photograph Descriptions

* 1. Damaged insulation 2. Close up of the damage 3. Belzona repair after 14 years in service 4. Belzona repair after 14 years in service ,

Application Situation

Insulated heating and ventilation ductwork on a university roof.

Application Method

Application was carried out in accordance with Belzona System Leaflet VPF-12.

Belzona Facts

Belzona 3211 offers outstanding protection from the elements, including UV exposure. It is micro-porous and will prevent liquid from penetrating through it while allowing any moisture to evaporate, so maintaining thermal efficiency and reducing CUI. This application was photographed in 2017, after 14 years in service. Still in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com


BELZONA
 Repair • Protect • Improve