

BELZONA PROTECTS FLANGES FOR GAS WORKS

ID: 7554

Industry: Oil & Gas
Application: GSS-Gaskets, Seals and Shims
Substrate: Mild Steel Flange
Products: * Belzona 3411 (Encapsulating Membrane),

Customer Location: Glasgow, Scotland
Application Date: June 2017

Problem

The Customer required a solution that would protect the flange from corrosion whilst still allowing access for inspection at a later date.



Photograph Descriptions

- * 1. Flange with void taped ,
- * 2. First coat during application ,
- * 3. First coat applied ,
- * 4. Second coat applied ,

Application Situation

A section of pipework had an exposed flange that was deemed to be susceptible to corrosion.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet GSS-11.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve

Belzona Facts

The Belzona solution allows the flange to be protected and then accessed when required for maintenance or inspection. Traditional painting of the flange would leave it inaccessible and may not completely encasulate the flange potentially allowing corrosion to still occur.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

