

Belzona Repairs Concrete Footing

ID: 7564

Industry: Buildings & Structures
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Concrete and Steel Reinforcement
Products: * Belzona 4111 (Magma-Quartz),

Customer Location: Construction company, Slovakia
Application Date: 2006

Problem

The footing was damaged by impact, this caused instability on the machine which meant it could not be used.



Photograph Descriptions

- * 1. Destroyed concrete footing. ,
- * 2. Belzona 4911 (TX Conditioner) application ,
- * 3. Repair in progress ,
- * 4. Belzona 4111 used to rebuild the base ,

Application Situation

The concrete footing of a cutting machine in a large workshop.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-9.

Belzona Facts

The Belzona concrete repair allowed the machinery to be back online in only 4 days, compared to the possible 28 day cure time for concrete. The Belzona materials also have greater impact resistance to protect from future damage.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve