

Belzona Protects Settlement Tank

ID: 7565

Industry: *General Industry*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Steel*
Products: ** Belzona 5811 (Immersion Grade) ,*

Customer Location: *Pharmaceutical Company, Slovakia*
Application Date: *2010*

Problem

Erosion/corrosion damage was affecting the normal operation of the equipment



Photograph Descriptions

- * 1. Mixing Basin ,
- * 2. Extent of damage to the basin ,
- * 3. Blasting of the basin ,
- * 4. Completed application ,

Application Situation

Damage to the tank and mixing equipment

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC 3.

Belzona Facts

The Customer required a fast, high quality solution to repair the basin. Belzona provided an effective solution to not only repair the basin and mixing apparatus, but also protect it in the long term, extending the lifetime. Spraying enabled the application to be completed within the available window.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

