

# Belzona Keeps The Cover On Annealing Oven

ID: 7566

Industry: *Steel & Metal Processing*  
Application: *ENC-Engines and Casings*  
Substrate: *Iron*  
Products: *\* Belzona 1121 (Super XL-Metal) ,*

Customer Location: *Metallurgy Company, Slovakia*  
Application Date: *2011*

## Problem

*The cover had distorted and did not sit correctly on the base and caused a CO2 leakage.*



## Photograph Descriptions

- \* 1. Annealing ovens ,
- \* 2. Surface preparation ,
- \* 3. Belzona 1121 application ,
- \* 4. Cover replaced ,

## Application Situation

Large annealing oven at a metal manufacturing plant.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet ENC - 7.

## Belzona Facts

Using the Belzona solution allowed the original equipment to be used as a former, ensuring a perfect fit. Rebuilding in this way also meant the line was back up sooner than expected.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve