

Belzona Pump Seating Repair

ID: 7600

Industry: *Steel & Metal Processing*
Application: *CEP-Centrifugal Pumps*
Substrate: *Iron casting*
Products: ** Belzona 1111 ,*

Customer Location: *Slovakia, metallurgic plant*
Application Date: *2014*

Problem

Corrosion, mechanical damage



Photograph Descriptions

- * 1. Damaged pump seating ,
- * 2. Machining of the Belzona 1111 ,
- * 3. Ready for customer ,

Application Situation

After long time operation the pump has worn down seating. Result is a big clearance of the bearing.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet CEP - 2

Belzona Facts

Welding of the seating is very difficult, takes a long time. Belzona solution means very good repair and result is that customer uses this Belzona repair also for another pumps.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve