

# Slide assembly with Belzona repair

ID: 7606

Industry: *Steel & Metal Processing*  
Application: *ENC-Engines and Casings*  
Substrate: *Steel*  
Products: *\* Belzona 1311 ,*

Customer Location: *Slovakia, metallurgic producer*  
Application Date: *2014*

## Problem

*Corrosion accelerated due to the inclusion of water and chemicals within the process*



## Photograph Descriptions

- \* 1. Damaged slide assembly ,
- \* 2. Belzona 1311 application ,
- \* 3. All surface were sanded down ,
- \* 4. Support ready to work ,

## Application Situation

Slide assembly were damaged from corrosion.

## Application Method

Application was carried out in accordance with modified Belzona Know-How System Leaflet ENC 7.

## Belzona Facts

Belzona was chosen because welding takes very long time with risk of the compromising the structural integrity.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve