

Cyclone coating protection with Belzona

ID: 7611

Industry: *Food & Drink*

Application: *SHM-Solids Handling Machinery*

Customer Location: *Slovakia, starch factory*

Application Date: *2011*

Substrate: *Steel*

Products: ** Belzona 1812 (Ceramic Carbide FP) ,*

Problem

Damaged cyclone



Photograph Descriptions

- * 1. Ready for repair ,
- * 2. Belzona 1812 application ,
- * 3. Belzona 1812 application detail ,

Application Situation

Milled corn material suffers and also adheres on the cyclone surface.

Application Method

Application was carried out in accordance with modified Belzona System Leaflet SHM- 13

Belzona Facts

Conventional welding to be out of service too long and also it is not long lasting solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve