

Rubber coating repair

ID: 7613

Industry: *Food & Drink*

Application: *SHM-Solids Handling Machinery*

Customer Location: *Slovakia, starch factory*

Application Date: *April 2021*

Substrate: *Rubber*

Products: *Belzona 2111 (D & A Hi-Build Elastomer)*

Problem

Damaged existing rubber coating



Steel construction



Belzona 2111 application



Construction in device



As the customer finds Belzona 2111 suitable for this application, he repeats other constructions at regular intervals.

Application Situation

Customer needed to put to the existing device with rubber coating in new construction.

Application Method

Application was carried out in accordance with Belzona 2111 instruction for use.

Belzona Facts

Conventional rubber coating repair is very complicated and takes a long time. Belzona 2111 shows better quality by compared with rubber coating.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve