

## Rubber coating repair

ID: 7613

Industry: *Food & Drink*

Application: *SHM-Solids Handling Machinery*

Customer Location: *Slovakia, starch factory*

Application Date: *April 2021*

Substrate: *Rubber*

Products: *Belzona 2111 (D & A Hi-Build Elastomer)*

### Problem

*Damaged existing rubber coating*



Steel construction



Belzona 2111 application



Construction in device



As the customer finds Belzona 2111 suitable for this application, he repeats other constructions at regular intervals.

### Application Situation

Customer needed to put to the existing device with rubber coating in new construction.

### Application Method

Application was carried out in accordance with Belzona 2111 instruction for use.

### Belzona Facts

Conventional rubber coating repair is very complicated and takes a long time. Belzona 2111 shows better quality by compared with rubber coating.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve