

Large storage tank protected with Belzona

ID: 7618

Industry: Chemical & Petrochemical
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Steel
Products: * Belzona 5811 (Immersion Grade) ,
* Belzona 1111 (Super Metal) ,

Customer Location: Petrochemical company, Slovakia
Application Date: 2015

Problem

The tank had been in service for twenty years and was suffering extensive corrosion damage



Photograph Descriptions

- * 1. Tank after 20 years. ,
- * 2. Blasting of the basin ,
- * 3. Visible damages after blasting ,
- * 4. Belzona 5811 coating applied in 2 layers ,

Application Situation

Crude oil storage tank

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC 3 & TCC-5

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Belzona Facts

Customer needed quick and quality repair. All protection was realized with Belzona 5811. Deep corrosion was rebuilt with Belzona 1111.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

