

Machine for cellulose production levelling

ID: 7621

Industry: *Pulp & Paper*
Application: *GSS-Gaskets, Seals and Shims*
Substrate: *Concrete*
Products: *Belzona 5811 (Immersion Grade)*

Customer Location: *Cellulose production plant, Slovakia*
Application Date: *July 2016*

Problem

Machine anchor and balance



Bases of the machines have to be seated on the correct place

Every possible leakage had to be close

Injection

Ready to work

Application Situation

Customer wanted to anchor a new machine for cellulose production. New machine has to be balanced.

Application Method

Application was carried out in accordance with Belzona 5811 Instruction for use.

Belzona Facts

Bases of the machines have to be seated on the correct place, then Belzona 5811 was injected to fix the bases.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve