

Belzona SuperWrap II Patch Saves Tank


ID: 7633

Industry: *General Industry*
Application: *VPF-Valves, Pipes and Fittings*
Substrate: *Carbon Steel*
Products: ** Belzona SuperWrap II System ,*
** Belzona 5811 (Immersion Grade) ,*

Customer Location: *Tarragona, Spain*
Application Date: *August, 2016*

Problem

Several areas of the tank had a loss of metal thickness due to corrosion under insulation.



Photograph Descriptions

- * 1- The problem. ,
- * 2- Setup to gain access. ,
- * 3- Finished patch repair. ,
- * 4- Overcoating with Belzona 5811. ,

Application Situation

A carbon steel storage tank (6m in diameter and 10m high) on a manufacturing plant, stored a water soluble non ionic soil release polyester for liquid detergents and cleaners.

Application Method

Application was carried out in accordance with a modified version of Belzona System Leaflet VPF-11. The repair was then overcoated with Belzona 5811 to give an aesthetically pleasing finish.

Belzona Facts

The Engineering and Maintenance Department requested a solution according to recognised standards. Belzona SuperWrap could be installed according to ISO 24817 with a 10-year lifetime and engineered design.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve