

Belzona Repair of Rail Print Interface on a Single Point Mooring Turret

ID: 7643

Industry: Marine

Customer Location: India

Application:

Application Date: December, 2017

Substrate: ABS EH36 (normalized carbon steel)

Products: * Belzona 1111 (Super Metal) ,

Problem

Severe pitting, galvanic and crevice corrosion on the rail support flange. Welding was not an option due to the location of the damage and the need for the surface to be accurately flat for the proper sitting of the rails.



Photograph Descriptions

- * Single Point Mooring Buoy and problem area. ,
- * Details of the pitting/crevice corrosion underneath the rail. ,
- * Surface preparation and application. ,
- * Completed application. ,

Application Situation

Repair of the support flange for the rail on a mooring buoy turret.

Application Method

The surface preparation was carried out by power brushing and grinding deep crossed pattern grooves. Application was done manually with Belzona applicators, plugging the holes where the rails will be bolted to the structure. Leveling of the surface was done with a flat plate segment and side flat guide bars with a width of about 175 mm placed at the rail print area for leveling and

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

for flatness check.

Belzona Facts

Rebuilding the rail support flange with Belzona 1111 allowed the asset owner to save money and time. Welding would have been much more time and manpower consuming, while machining on site would have been very complicated, time consuming and costly. Apportioning new metal to rebuild the rail print wouldn't have solved the problem since the risk of galvanic corrosion would not have been eliminated. A Belzona 1111 rail print interface could be adopted in new fabricated turrets in order to extend the life span of the asset.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

