

BELZONA SPRUCES UP WHILE REPAIRS AND PROTECTS AN AIRPORT FOUNTAIN

ID: 7666

Industry:

Customer Location: *International Airport, Florida, USA*

Application:

Application Date: *Summer 2017*

Substrate: *Concrete*

Products: ** Belzona 5812DW (Blue) ,
* Belzona 4124 (Bulkfill) ,
* Belzona 5233 (Clear) ,*

Problem

Old marine paint used for the inside of the display fountain was a dull color and difficult to keep clean.



Photograph Descriptions

- * 1. Containment for the fountain to keep concrete dust away from the adjacent rental cars. ,
- * 2. Scarifying the inside of the fountain ,
- * 3. Applying Belzona 5233 clear ,
- * 4. Finished application and fountain started 3 days after application. ,

Application Situation

Fountain outside one of the terminals.

Application Method

The surface was prepared by scarifying concrete. Belzona 5233 (Clear) was applied to the rock face around the outside of the fountain. Some cracks were fixed by applying Belzona 4124. The inside of the fountain was coated with Belzona 5812DW (Blue).

Belzona Facts

The Customer wanted a blue coating for the inside of the fountain that would be easy to clean and would last under immersion. They also wanted the rock face on the side to be sealed with Belzona 5233 (Clear) and any cracks in the rock face were filled with Belzona 4124. The Customer wanted to use Belzona products due to the successful previous applications with the other fountains at this facility.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

Copyright © Belzona International Limited 2024