Belzona Spin Spray Applied Protective Coating for Scraper Traps

ID: 7681

Industry: Oil & Gas Customer Location: Oil Field, Saudi Arabia

Application: VPF-Valves, Pipes and Fittings Application Date: 2017 - 2018

Substrate: Carbon steel
Products: * Belzona 1391S,

Problem

Scraper traps, that launch and receive scrapers/pigs when the crude oil pipeline is being cleaned, required corrosion protection.









Photograph Descriptions

- * 1. Scraper trap prior to application.,
- * 2. Calibration.,
- * 3. First coat applied.,
- * 4. Application complete.,

Application Situation

A new HT crude oil transfer pipeline is being installed at an oilfield in Saudi Arabia. Belzona 1391S has been specified for the protection of 12 newly fabricated scraper traps, following a process vessels lining spec for the same customer.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-2 using spin spray application equipment.

Belzona Facts

Belzona 1391S offers excellent corrosion protection and can be easily applied by spray. 12 scraper traps have been protected with a Belzona coating in 2017 at a facility in the UK, with further applications continued in 2018 as the new scraper traps get fabricated. Recently, Belzona has perfected the design of the spin spray equipment parts. These parts can be inexpensively fabricated locally.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve