

Belzona Composite Ferry Wrap



ID: 7698

Industry: *Transport*
Application: *VPF-Valves, Pipes and Fittings*
Substrate: *Mild Steel*
Products: ** Belzona 1121 (Super XL-Metal) ,*
** Belzona 5821 ,*

Customer Location: *France*
Application Date: *November 2017*

Problem

Suffering from external corrosion



Photograph Descriptions

- * 1. Damaged pipe ,
- * 2. Belzona 1121 wrap in progress ,
- * 3. Composite Wrap complete ,
- * 4. Completed application ,

Application Situation

Ferry Pipe

Application Method

The application was carried out in accordance with Belzona system leaflet VPF-11. This was followed by over-coating with Belzona 5821.

Belzona Facts

The customer required a solution that was quick in order to get back into service.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve