

Cooling Tower protected thanks to Belzona

ID: 7734

Industry: Sugar
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Concrete
Products: * Belzona 4111 (Magma Quartz) ,
* Belzona 5811 (Immersion Grade) ,

Customer Location: Sugar Mill, France
Application Date: July 2018

Problem

General corrosion of the concrete basin



Photograph Descriptions

- * 1- Corrosion of the concrete and exposed steel re-bar ,
- * 2- Repair of the concrete work using Belzona 4111 ,
- * 3- Work completed with application of belzona 5811 ,
- * 4- Work completed ,

Application Situation

Cooling water basin

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15.

Belzona Facts

Belzona 4111 and 5811 are ideally suited for the long term protection of cooling water basins given their high adhesion values and excellent corrosion resistance and performance in immersion up to 50°C.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

