

Belzona provides a second life to this cooling tower

ID: 7737

Industry: *Steel & Metal Processing*
Application: *TCC-Tanks and Chemical Containment Areas*

Customer Location: *Metal processing plant, France*
Application Date: *May 2018*

Substrate: *Carbon Steel*

Products: ** Belzona 1221 (Super E-Metal) ,*
** Belzona 1121 (Super XL-Metal) ,*
** Belzona 5811 (Immersion Grade) ,*

Problem

External corrosion leading to significant wall thinning and localised through wall defects.



Photograph Descriptions

- * 1 - The cold bonding of metal plate to patch up thin areas ,
- * 2 - Wrap in progress ,
- * 3 - Wrap completed ,
- * 4 - Coating for further corrosion protection ,

Application Situation

Heat Exchanger - acid cooling tower. Operating pressure of 1 bar and temperature between 30 and 50C.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

Belzona Facts

Two towers were suffering from the same problem at the same time: through wall defects due to corrosion. The customer had one

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

spare ready (costing 90,000€) but could not afford to wait for a replacement one being given the 8 months lead time. The Belzona repair was completed in 4 days by a team of 3 technicians. The tower was put back in service within 72 hours. The Belzona repair (products + application) did cost one-third of the replacement cost (30,000€).

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

