

BELZONA UPGRADES TANK FARM FLOOR

ID: 774

Industry: *Buildings & Structures*

Customer Location: *AFB Pet Food Additive Manufacturer,
OFallon, MO*

Application: *FPA-Floor Problem Areas*

Application Date: *April 2006*

Substrate: *Concrete*

Products: *Belzona® 4131 (Magma Screed)*

Problem

Thin top layer of concrete delaminated allowing Bacteria growth and unacceptable appearance.



Photograph Descriptions

* Old concrete , * Start of application , * Finished job ,

Application Situation

Floor area around storage tanks

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet FPA-1

Belzona Facts

A long history of successful applications gave the customer confidence that this was the only practical solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve