

# BELZONA UPGRADES TANK FARM FLOOR

ID: 774

Industry: Buildings & Structures

Customer Location: AFB Pet Food Additive Manufacturer,  
OFallon, MO

Application: FPA-Floor Problem Areas

Application Date: April 2006

Substrate: Concrete

Products: Belzona® 4131 (Magma Screed)

## Problem

*Thin top layer of concrete delaminated allowing Bacteria growth and unacceptable appearance.*



## Photograph Descriptions

\* Old concrete , \* Start of application , \* Finished job ,

## Application Situation

Floor area around storage tanks

## Application Method

Application carried out in accordance with Belzona Know-How System Leaflet FPA-1

## Belzona Facts

A long history of successful applications gave the customer confidence that this was the only practical solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve