

Belzona Repairs Tank Leg Supports at a Distillery

ID: 7772

Industry: *Food & Drink*
 Application: *TCC-Tanks and Chemical Containment Areas*
 Substrate: *Steel*
 Products: ** Belzona 5811 (Immersion Grade),*

Customer Location: *United Kingdom*
 Application Date: *2018*

Problem

Several VAT tank leg supports were corroded due to the break down of the original paint system. Some tanks had already been condemned due to metal loss and through wall defects in the tank supports.



Photograph Descriptions

- * Damaged tank leg supports ,
- * Damaged tank leg supports ,
- * 1st coat of Belzona 5811 ,
- * Application after 1 year in service ,

Application Situation

VAT tank leg supports at a distillery.

Application Method

The previous paint was removed by saturation blasting to keep the dust levels down on-site. The VAT legs were then coated by hand with Belzona 5811 in accordance with a modified version of Belzona Know-How System Leaflet TCC-5.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com


BELZONA
 Repair • Protect • Improve

Belzona Facts

This system provides a long-term corrosion resistance and an aesthetically pleasing finish.

The application was re-visited 1 year later, and found to still be forming with no damage or repairs required.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

