

Belzona Protects Washing Powder Hoppers

ID: 7800

Industry:

Application: TCC-Tanks and Chemical Containment Areas

Substrate: Carbon steel

Products: * Belzona 1331 ,

Customer Location: Czech Republic

Application Date: February 2017

Problem

The citric acid content of the washing powder was causing erosion-corrosion to the supply hoppers



Photograph Descriptions

- * Application in progress, showing the unprotected substrate ,
- * Closeup of the finished coating ,
- * The equipment at hand ,

Application Situation

Hoppers supplying storage bins in the manufacture of washing powder

Application Method

The application was carried out in accordance with Belzona System Leaflet TCC-3. Belzona 1331 was applied by brush.

Belzona Facts

A Belzona coating was chosen as the Customer sought after a long-term corrosion protection against citric acid, whilst also having the durability to withstand dry abrasion from powder.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve