

# Chimney restored with Belzona

ID: 7856

Industry: Power  
Application: FBC-Fans, Blowers and Compressors

Customer Location: Baltic region, Poland  
Application Date: 2018

Substrate: Brickwork  
Products: \* Belzona 5111 (Ceramic Cladding) (Special RAL3000) ,  
\* Belzona 5911 (Ceramic Cladding Conditioner) ,

## Problem

The 120-meter high chimney of the plant's combined heat and power plants required a new more durable coating protection. Previous coatings were very quickly tarnished and damaged.



## Photograph Descriptions

- \* The deteriorated chimney ,
- \* The application underway ,
- \* The completed job ,
- \* The completed job ,

## Application Situation

Oil refinery chimney, northern Poland

## Application Method

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

The application was carried out in Accordance with Belzona System Leaflet FBC-02 The chimney was cleaned, the old paint was removed by abrasive blasting to achieve a good surface profile. Then, Belzona 5911 Ceramic Cladding Conditioner was applied. Two layers of Belzona 5111 (Ceramic Cladding) coating were then applied onto a conditioned surface. The total area to be covered was 4,000 square meters.

## Belzona Facts

The customer is a long term good customer. However, it was necessary to convince them to buy a coating almost three times more expensive than the previous coatings. They were convinced that the coating lasts longer (Belzona 5111 has a very high albedo – 0.89 thanks to which it reflects a significant part of solar radiation) and that the Belzona 5111 coating will be clean for longer and very visible.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

