BELZONA GETS TO GRIPS WITH SAFETY AT AN INTERNATIONAL CONFERENCE CENTRE

ID: 786

Industry: *Buildings & Structures*
Application: *FPA-Floor Problem Areas*
Substrate: *Ceramic tiles*
Products: *Belzona® 4131 (Magma-Screed) ,*
Belzona® 4411 (Granogrip) ,
Belzona® 9221 (Surefoot Aggregate) ,

Customer Location: *International Conference Centre-UK*
Application Date: *June 2003*

Problem
The finish on the tiles which made up the steps was a slip hazard when wet. In addition to this the steps were subjected to heavy foot traffic and misuse by skateboards, necessitating renovation to a condition reflecting the status of the International Conference Centre.

Photograph Descriptions

* Original condition of the entrance steps. ,
* Safety Grip areas masked off. ,
* The finished application. ,
* Application after 6 years of service. ,

Application Situation
Main entrance steps of Conference Centre

Application Method
The application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 and FPA-8.

Belzona Facts

The customer was extremely pleased with the aesthetic appearance of the application, which aside from meeting their safety needs, matched the Organisations Logo. After 6 years of arduous service Belzona is still providing excellent performance and the rough surface prevents damage from skateboarders.

BELZONA®
Repair • Protect • Improve