

BELZONA GETS TO GRIPS WITH SAFETY AT AN INTERNATIONAL CONFERENCE CENTRE

ID: 786

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Ceramic tiles
Products: * Belzona® 4131 (Magma-Screed) ,
 * Belzona® 4411 (Granogrip) ,
 * Belzona® 9221 (Surefoot Aggregate) ,

Customer Location: International Conference Centre-UK
Application Date: June 2003

Problem

The finish on the tiles which made up the steps was a slip hazard when wet. In addition to this the steps were subjected to heavy foot traffic and misuse by skateboards, necessitating renovation to a condition reflecting the status of the International Conference Centre.



Photograph Descriptions

- * Original condition of the entrance steps. ,
- * Safety Grip areas masked off. ,
- * The finished application. ,
- * Application after 6 years of service. ,

Application Situation

Main entrance steps of Conference Centre

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 and FPA-8.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com


BELZONA®
 Repair • Protect • Improve

The customer was extremely pleased with the aesthetic appearance of the application, which aside from meeting their safety needs, matched the Organisations Logo. After 6 years of arduous service Belzona is still providing excellent performance and the rough surface prevents damage from skateboarders.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

