

HOMELAND SECURITY RUSH JOB COMPLETED WITH BELZONA

ID: 788

Industry: Military
Application: FPA-Floor Problem Areas
Substrate: Steel deck & bulkhead
Products: Belzona® 4111 (Magma Quartz)

Customer Location: U.S. Coast Guard
Application Date: July 2006

Problem

This job had to be completed the same day problem identified so that the boat could sail on time.



Photograph Descriptions

* The boat , * One of two problem areas , * Starting the repair , * Completed ,

Application Situation

Two old shower stalls on the boat allowed water to seep behind the stall walls rusting a 24" x 4" hole in the deck & leaked water into the engine room. The bulkhead was rusting badly as well

Application Method

Belzona® 4111 applied in accordance with Belzona System Leaflet FPA-1 & the new shower base & sides installed in front of the repair while the material was still wet.

Belzona Facts

The expensive alternative was to cut out a large chunk of deck plate & bulkhead and weld in new pieces. There was not enough time for this and the expense would have been high.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024