

Belzona Offers a Peace of Mind to a Private Villa Owner

ID: 7886

Industry: *Buildings & Structures*

Application: *FPA-Floor Problem Areas*

Substrate: *Concrete*

Products: ** Belzona 4111 (Magma Quartz) ,
* Belzona 5891 (HT Immersion Grade) ,*

Customer Location: *Saudi Arabia*

Application Date: *2017*

Problem

Poorly finished concrete walls and floors.



Photograph Descriptions

- * The potable water tank before the application. ,
- * Another view of a tank before the application. ,
- * Complete application. ,

Application Situation

Five underground potable water storage tanks within a luxury villa.

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-1, Belzona 4111 was used to repair the poorly finished concrete walls and floors of the tanks and Belzona 5891 was used to coat the internal

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025

surfaces of the tanks.

Belzona Facts

The customer was satisfied with both the product finish and the way the repair and coating were carried out. After the initial cleaning the water was crystal clear and odourless. The tanks were opened after a 1 year in service for cleaning and the coatings were found sound and intact.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

