

Primary Crusher Base Repaired with Belzona 4111 and Belzona 4151

ID: 7914

Industry: Mining & Quarrying

Customer Location: Copper Mine, Brazil

Application: RPA-Roof Problem Areas

Application Date: 2018

Substrate: Concrete

Products: * Belzona 4111 (Magma-Quartz),
* Belzona 4151 (Magma-Quartz Resin),
* Belzona 4911 (Magma TX Conditioner),

Problem

Excessive vibration of the crusher caused the concrete base to crack which could potentially compromise the functionality of the machinery.



Photograph Descriptions

* Damaged base of the crusher. The perimeter of the base rebuilt with a regular mix of Belzona 4111. A fluid mixture of Belzona 4111 and Belzona 4151 resin used to fill in the void and have it self-level in the base. Foundation of primary crusher repaired with Belzona 4111 and Belzona 4151 ,

Application Situation

Base of a primary crusher at a mine.

Application Method

Using an impact hammer drill, the first two layers of concrete were removed to reach the steel reinforcement structure. Prior to application of Belzona 4911 (Magma TX Conditioner), area was cleaned and degreased with a solvent, compressed air was also used to have the entire repair area free of loose debris and dust. The perimeter of the repair area was rebuilt with a regular mix of Belzona 4111, and after that, a fluid mix of Belzona 4111 with extra Belzona 4151 was used to fill the void and self-level the base of the equipment.

Belzona Facts

The Customer was very pleased with the system implemented because it reduced the vibration of the equipment. This is one of the solutions offered on a regular basis for local mining plants in Brazil, they are success cases that give the Customer confidence and reliability.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com



For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

