

Belzona repairs leaking fire water pipe lines of a navy ship

ID: 7992

Industry:
Application:
Substrate: *Ni, Chromium alloy*
Products: ** Belzona 1212 ,
* Belzona 9341 reinforcement tape ,*

Customer Location: *NAVY*
Application Date: *2019*

Problem

The pipe was leaking causing local flooding in the engine room. The navy tried to seal the leaking pipe with other products, but this had failed & was still leaking. So they contact Belzona



Photograph Descriptions

* 1) Leaking pipe 2) After surface preparation 3) Repair in progress 4) Completed application ,

Application Situation

The fire water pump piping was leaking with no replacement pipe available

Application Method

The application was carried out in accordance with Belzona Know-How system Leaflet VPF 11

Belzona Facts

Belzona was the only fast and effective solution to the problem until the new pipe arrive

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

