Belzona helps in the Restoration of an Irrigation Pipeline

ID: 8049

Industry: Fluid Flow Customer Location: Italy

Application: TCC-Tanks and Chemical Containment Application Date: May 2019

Areas

Substrate: Carbon Steel

Products: * Belzona 1121 (Super XL-Metal),

* Belzona 1982 (SuperWrap 2),

* Belzona 9381 , * Belzona 5821 ,

Problem

The internal walls of the pipeline were suffering from serve corrosion and wear over time. Outright replacement of the pipe wasn't an option as the pipeline was burried 10 meters below ground and embedded within a conctete structure.









Photograph Descriptions

- * View after sandblasting ,
- * Application of Belzona 1121,
- * Application of Belzona 1982/9381,
- * Application of Belzona 5821,

Application Situation

Restoring an old irrigation pipline within a pumping station.

Application Method

This application was carried out in accordance with system leaflet TCC-05. The internal walls of the pipeline were sandblasted and

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com



then any pitted areas were filled in with Belzona 1121. A Belzona SW2 system was then fabriacted to create a "pipe within a pipe" to restore the existing pipeline. Finally 2 coats of Belzona 5821 was applied over the SW2 system to provide corrosion and erosion resistance.

Belzona Facts

The Belzona solution avoided a costly and complex replacement of the system and allowed the pipeline to be put back in service within a few days. Now the plant will be able to cater to the needs of the farmers and avoid lentgthy downtime in the future.

www.belzona.com