

# Belzona helps in the protection of a surface under the granule scraper.

ID: 8060

Industry: *General Industry*

Customer Location: *Puławy, Poland*

Application: *FPA-Floor Problem Areas*

Application Date: *2019*

Substrate: *Concrete*

Products: *\* Belzona 4151 (Magma Quartz Resin) ,  
\* Belzona 5811 (Immersion Grade) ,*

## Problem

*Corrosion of concrete and surface due to the scraper moving the granules around the area.*



## Photograph Descriptions

- \* Application Area Picture ,
- \* Area to be treated under the scraper ,
- \* Applying Belzona 4151 & Belzona 5811 ,
- \* Application Completed ,

## Application Situation

Modernisation and protection of the surface area under the granule scraper.

## Application Method

Repair any surface damaged concrete areas with Belzona 4151 Sealing the surface under the scraper using Belzona 5811.

## Belzona Facts

Long-lasting chemical resistance with Belzona 5811 securing the surface under the scraper.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)



---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

