

Belzona Magma Foundations Repair at Cement Factory

ID: 8070

Industry: Mining & Quarrying

Customer Location: Southern Poland

Application: WPA-Wall Problem Areas

Application Date: 2019

Substrate: Concrete

Products: * Belzona 4111 (Magma Series) ,

Problem

During long-term operation under varying climatic conditions and high temperatures, the foundation (supports, beams) was degraded under the head of the clinker furnace.



Photograph Descriptions

- * Degraded Concrete ,
- * Metal Mould to pour Belzona 4111 ,
- * Applying Belzona 4111 ,
- * Finished Job. ,

Application Situation

Repair of the foundations of the clinker furnace head at a large cement factory in Poland.

Application Method

The application was completed in accordance with an adapted version of Belzona System Leaflet WPA-4. A metal mould was created around the affected area to pour the Belzona 4111 into to ensure a perfect finish.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Offered Belzona due to its outstanding long-term abrasion resistance and fast curing time.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

