

# Corrosion Protection 2 x Industrial Storage Tanks with Belzona 5811



ID: 8073

Industry: Water / Wastewater  
Application: TCC-Tanks and Chemical Containment Areas  
Substrate: Steel  
Products: \* Belzona 5811 (Immersion Grade),

Customer Location: Poland  
Application Date: 2019

## Problem

Corrosion on the internal linings of two large storage tanks at a large industrial plant in Poland.



## Photograph Descriptions

<div>1. One of the storage tanks to be coated.</div>

\* 2. Belzona 5811 applied internally. ,

\* 3. Testing dry film thickness. ,

\* 4. Application complete on the internal lining. ,

## Application Situation

Corrosion protection for 2 DEMI water tanks (Total area - 1520 m2, 2000m3)

## Application Method

The application of Belzona 5811 was completed in accordance with Belzona System Leaflet TCC-5.

## Belzona Facts

Long-term protection against corrosion on the tanks.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

Copyright © Belzona International Limited 2024