

Corrosion Protection 2 x Industrial Storage Tanks with Belzona 5811


ID: 8073

Industry: Water / Wastewater
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Steel
Products: * Belzona 5811 (Immersion Grade),

Customer Location: Poland
Application Date: 2019

Problem

Corrosion on the internal linings of two large storage tanks at a large industrial plant in Poland.



Photograph Descriptions

<div>1. One of the storage tanks to be coated.</div>

* 2. Belzona 5811 applied internally. ,

* 3. Testing dry film thickness. ,

* 4. Application complete on the internal lining. ,

Application Situation

Corrosion protection for 2 DEMI water tanks (Total area - 1520 m2, 2000m3)

Application Method

The application of Belzona 5811 was completed in accordance with Belzona System Leaflet TCC-5.

Belzona Facts

Long-term protection against corrosion on the tanks.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve