

Belzona secures a lifting winch

ID: 8075

Industry:

Application: *SHM-Solids Handling Machinery*

Customer Location: *France*

Application Date: *August 2017*

Substrate: *Steel*

Products: ** Belzona 7111 ,*

Problem

Chocking of heavy machinery winch.



Photograph Descriptions

- * Dredging vessel ,
- * Area marked and dammed, ready for application ,
- * Pouring in progress ,
- * Completed application ,

Application Situation

Lifting winch being secured on the deck of a dredging vessel

Application Method

The installation was carried in accordance with Belzona System Leaflet GSS-12.

Belzona Facts

The 4 supporting pads were chocked using Belzona 7111 in order to ensure optimum load transmission as well as long term

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve

protection against vibration. The fast curing properties of the material were a key factor for the operator of the ship.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

