

# BELZONA REPAIRS GEAR BOX OF DREDGER

ID: 808

Industry: *Marine*  
Application: *ENC-Engines and Casings*  
Substrate: *Cast Iron*  
Products: *Belzona® 1111 (Super Metal)*

Customer Location: *Dredger, Egypt*  
Application Date: *August 2006*

## Problem

*Bearing housing of the gear box was badly worn due to bearing failure.*



## Photograph Descriptions

\* View of the dredger cutter shaft gear box , \* Worn out bearing housing , \* Form was applied, then Belzona injected through the former , \* Gear box bearing housing perfectly rebuilt ,

## Application Situation

Gear Box of dredger cutter shaft.

## Application Method

Application was carried out in accordance with modified version of Belzona Know-How System Leaflet ENC-3a.

## Belzona Facts

Belzona successfully repaired the bearing housing insitu without machining which would have been difficult due to the large size of the gearbox.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve