

Belzona 1321 in use at a large Sawmill in the Baltics

ID: 8093

Industry: *General Industry*

Customer Location: *Estonia*

Application: *SHM-Solids Handling Machinery*

Application Date: *2018*

Substrate: *Mild steel*

Products: ** Belzona 1321 (Ceramic S- Metal),
* Belzona 9211 (Supergrip Aggregate),*

Problem

Worn lumber transfer rollers lack the required grip to transfer lumber quickly and efficiently. This inefficiency affected the ability of transferring lumber from one part of the plant to another, which was affecting revenue and production levels.



Photograph Descriptions

- * Rolls grip system worn smooth ,
- * Application of Belzona 1321 and Belzona 9211 ,

Application Situation

Grip Rollers in Lumber Mill were worn causing inefficient transfer of lumber system.

Application Method

The application was carried out in accordance with Belzona Know-How Leaflet SHM-12

Belzona Facts

These rolls are typically in service 1-2 years depending on the sawmill activity and type of lumber produced

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

