

Belzona Resurfaces Deteriorated Bike Rack at UK College Facility

ID: 8124

Industry: Commercial Facilities

Application: FPA-Floor Problem Areas

Substrate: Concrete


Products: * Belzona 4131 (Magma Screed) ,
* Belzona 4911 (Magma TX Conditioner) ,

Customer Location: Yorkshire, UK

Application Date: April 2019

Problem

The Facilities Management team at the college wanted to resurface the bike rack as it was causing a trip hazard for those using the area. Not only that, but they wanted to improve the aesthetics for the staff and visitors using the facility.



Photograph Descriptions

- * Bike rack showing large areas of spalled and deteriorated concrete ,
- * Application of Belzona 4131 (Magma Screed) ,
- * Resurfacing the final area of the bike rack ,
- * Revisited several weeks later and in perfect condition ,

Application Situation

The bike rack at a UK college facility was showing significant signs of deterioration, with vast areas of the concrete surface spalled or cracked due to wear and weathering.

Application Method

The metal rack, which was bolted in the concrete, was removed and the surface was inspected for areas of crumbling and loose material. Any loose concrete was chiselled away, ensuring a solid surface. Next, the entire bike rack was pressure washed, removing any contaminants and plant growth. Once dry, Belzona 4911 was used to condition the concrete prior to the application of Belzona 4131. Working across in sections, the bike rack was resurfaced using a float to provide a smooth finish.

Belzona Facts

The Facilities Management team had a week available to carry out necessary repairs during the college's half-term break. The Belzona mortar repair systems were the ideal choice in this instance, being able to receive foot traffic after just a matter of days

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

curing and providing a long-term solution to the issue.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

