

Shopping centre step with Belzona grip system

ID: 8128

Industry: Buildings & Structures

Application: FPA-Floor Problem Areas

Substrate: Stone

Products: * Belzona 4411 Granogrip ,
* Belzona 9221 Surefoot white ,

Customer Location: Paisley, Scotland

Application Date: October 2018

Problem

Limited closure times were available, any solution had to be fast back to service.



Photograph Descriptions

- * Close up of application ,
- * Top down view ,
- * Bottom view ,

Application Situation

A set of stone steps leading to the entrance of a shopping centre was identified as a potential slip hazard in wet or icy conditions. A hard wearing, easy to see grip system was required to give positive traction to pedestrians using the steps.

Application Method

The step nosings were abraded with a floor grinder. The Belzona 4411 system was then applied by brush before the Belzona 9221 was sprinkled on top to form the grip system

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

The application was able to be carried out over one day so minimal disruption to the area was caused

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

